# MATERIAL SAFETY DATA SHEET

PRODUCT NAME: HEUMINUM & GREVHNIZED PRIMER HMIS CODES: H F R P

PRODUCT CODE: 5D-946

H کا ک کے

MANUFACTURER'S NAME: Lanco Mifg.

ADDRESS: URB. APONTE #5 SAN LORENZO PR, 00754

EMERGENCY PHONE: 1-800-424-9300 INFORMATION PHONE: (787) 736-4221

NAME OF PREPARER : VICTOR M. HERNHINDER DATE REVISED : 02-02-99

======= SECTION II - HAZARDOUS INGREDIENTS/SARA III INFORMATION ========

HAZARÓÐUS COMPONENTS	Cas Number		ional exposul acaih tlv	RE LIMITS OTHER	VAPOR PRESS		
*METHYLBENZENE *COBALTO 12% EXKIN #2	108-88-3 Mixture 96-29-7	100 PPM 500 PPM N/A	50 PPM 100 PPM N/A	N/A N/A N/A	22.0 1.0 18.0	<b>68F</b> 77F 115F	2 { <b>0.5</b> %

<sup>\*</sup> Indicates toxic chemical(s) subject to the reporting requirements of section 313 of Title III and of 40 CFR 372.

SPECIFIC GRAVITY (H2O=1): BOILING RANGE: ದರ್ವ ಕಂ 380 Deg F EVAPORATION RATE: SLUWER THAN ETHER VAPOR DENSITY: HEAVIER THAN AIR

COATING V.O.C. : 3.70 LB/GL ( 443 G/L) 3.50 LB/GL ( 419 G/L) MATERIAL V.O.C.:

SOLUBILITY IN WATER: NON SOLUBLE APPEARANCE AND ODOR: WHITE COLUR

METHOD USED: ICC FLASH POINT: 45 Deg F FLAMMABLE LIMITS IN AIR BY VOLUME- LOWER: 1.2% UPPER: /.0%

EXTINGUISHING MEDIA: FORM, COR, DRY CHEMICAL, WATER FOG

SPECIAL FIREFIGHTING PROCEDURES

RESPIRATORY EQUIPMENT SHOULD BE WORN TO AVOID INHALATION OF CONCENTRATED VAPOR WATER SHOULD NOT BE USED EXCEPT AS FOR TO KEEP NERBY CONTAINERS COOL.

UNUSUAL FIRE AND EXPLOSION HAZARDS

EXTREMELY FLAMMABLE. VAPORS MAY IGNITE EXPLOSIVELY AND/OR CAUSE FLASH FIRES. ELIMINATE SOURCES OF IGNITION. NO SMOKING. USE ADEQUATE CROOS VENTILATION SUFFICIENT TO REMOVE ODOR OF SOLVENT AND VAPORS.

STABILITY: STABLE CONDITIONS TO AVOID

EXCESSIVE HEAT, POOR VENTILATION, CORROSIVE ATMOSPHERES, EXCESSIVE AGING.

INCOMPATIBILITY (MATERIALS TO AVOID)

STRONG DIDIZING AGENTS, STRONG ACIDS AND DIDIZING MATERIALS, ALKALINE MATERIALS.

HAZARDOUS DECOMPOSITION OR BYPRODUCTS CARBON MONOXIDE, CARBON DIOXIDE, AND DXIDES OF NITROGEN.

HAZARDOUS POLYMERIZATION: WILL NOT DCCOR NOW.

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

ACUTE SIGS OF OVEREXPOSURE COULD BE MEADACHE, DIZZINESS MAUSEA, UPPER RESPIRATORY DRYNESS O IRRITATION, DROWSINESS, MENT AL DEPRESSION OF MARCOSIS.

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE EYE CONTACT: SEVERE IRRITATION, TEARING, REDNESS AND BLURRED VISION.

SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE SKING CONTACT: CAN DRY AND DEFAT SKIN CAUSING CRACKS, IRRITATION, AND DERMATITIS,

INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE INGESTION: CAN CAUSE GASTROINTESTINAL IRRITATION, VONITING, NOUSEA, AND DIARRHEA.

HEALTH HAZARDS (ACUTE AND CHRONIC)

INHALATION-DIZZYNESS, BREATHING DIFFICULTY, HEADACHES, & LOSS OF COORDINATION. EYE CONTACT-SEVERE IRRITATION, TERING, RED NESS, AND BLURRED VISION. SKIN CONTACT- CAN DRY AND DEFAT SKING CRUSING CROCKS, IRRITATION AND DERMITITIS. INGESTION-CAN CAUSE GASTROINTESTINAL IRRITATION. VONITING NAUSSEA & DIARRHEA. NO CHRONIC HEALTH EFFECTS.

CARCINOGENICITY: NTP? NU IARC MONOGRAPHS? NO OSHA REGULATED? NO NOME

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE AMESTHESIA, RESPIRATORY TRACT TRITTATION, DERRITTITS, NAUSEA, VONITING.

EMERGENCY AND FIRST AID PROCEDURES

INHALATION OVEREXPOSURE - MOVE PERSON TO FRESH AIR. IF BREATHING STOPS, APPLY ARTIFICIAL RESPIRATION AND SEEK INMEDIATE NEDICAL ATENTION. EYE CONTACT- FLUSHMITH LARGE QUANTITIES OF WATER FOR 15 MINUTES. SKIN CONTACT- MASH THOROUGHLY MITH SOAP AND WATER AND SEE A DOCTOR. INGESTION DO NOT INDUCE VOWITING, CAN CAUSE CHEMICAL PHEUMONITIS AND PULMONARY EDENA. CONTACT PHYSICAL INMEDIATELY.

======== SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE ==========

# STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

ELIMINATE IGNITION STURGES, PROVIDE 6000 VENTILATION, DIKE SPILL AREA AND ABSORBENT EARTH OR SAMOUST TO SPILLED LIGHTD. THOROGHLY WET WY WATER AND MIX.

# WASTE DISPOSAL METHOD

COLLECT ABSORBENT/ MATER/ SPILLED LIQUID MILITURE INTO METAL CONTAINERS AND ADD ENDUGH WATER TO COVER. CONSULT LOCAL, STA TE & FEDERAL HAZARDOUS WASTE REGULATION BEFORE DISPOSING INTO APPROVED HAZARDOUS WASTED LANDFILLS. DBEY RELEVANT LAW.

#### PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

KEEP CONTAINERS CLOSED WHEN NOT IN USE. STORE 68-95 F OUT OF SUN, USE ADEQUATED VENTILATION TO AVOID BREATHING VAPOR WHE N COVER REMOVED, KEEP AWAY EXESSIVE HEAT AND OPEN FLAMES.

### OTHER PRECAUTIONS

GROND ALL EQUIPMENT WHEN HANDLING FLAMMABLE SOLVENT BORNE MATERIALS, SMOKING IN AREA WHERE THIS MATERIAL IS USED SHOULD BE STRICTLY PROHIBITED.

#### RESPIRATORY PROTECTION

WHEN SPRAYING THIS MATERIAL USE A NIOSH APPROVED CARTRIDGE RESPIRATOR OR GAS MASK SUITABLE TO KEEP AIRBORNE MISTS AND VA POR CONCENTRATIONS BELOW THE TIME WEIGHTED THRESHOLD LINIT VALUES. WHEN USING IN POORLY VENTILATED AND CONFINED SPACES, USE A FRESH-AIR SUPPLYING RESPIRATOR OR A SELF- CONTAINED BREATHING APPARATUS.

#### VENTIL ATTON

SUFFICIENT 10 KEEP WORKROOM CONCENTRATION BELOW TLV. VENTILATION EQUIP. MUST BE EXLPOSION PROOF.

# PROTECTIVE GLOVES

CHEMICALS RESISTANT GLOVES.

#### EYE PROTECTION

USE CHEMICAL SAFETY BLASSES, GOBBLES, AND FACESHIELDS FOR EYE PROTECTION.

# OTHER PROTECTIVE CLOTHING OR EQUIPMENT

USE IMPERMEABLE APRONS AND PROTECTIVE CLOTHING WHENEVER POSSIBLE TO PREVENT SKIN CONTACT. THE USE OF HEAD CAPS WHENEVER POSSIBLE IS STRENGLY RECOMMENDED.

# WORK/HYGIENIC PRACTICES

EYE WASHES AND SAFETY SHOWERS IN THE WORKPLACE IS RECOMMENDED.

# DISCLAIMER

The information contained herein is based on data believed by this company to be accurate, but we do not assume any inability for its accuracy. We neither suggest nor guarantee that any nazards mentioned are the only ones which exist. The manner of that use and whether there is any infringement of patents is the sole responsibility of the user.